

Site: Gary Development Landfill – 459 N. Cline Avenue, Gary, Indiana

Description: Site Reconnaissance on September 5, 2012

Photographs taken by: U.S. Environmental Protection Agency



Photo 1 (100_0003): Parking entrance to Site from Vulcan (view facing east)

Location: Gary Development Landfill, Gary, Indiana

Date/Time Taken: 09/05/2012 at 10:21 AM



Photo 2 (100_0004): Abandoned building at southwest corner of site (view facing northwest)

Location: Gary Development Landfill, Gary, Indiana

Date/Time Taken: 09/05/2012 at 10:26 AM

Site: Gary Development Landfill – 459 N. Cline Avenue, Gary, Indiana

Description: Site Reconnaissance on September 5, 2012

Photographs taken by: U.S. Environmental Protection Agency



Photo 3 (100_0005): Interior of abandoned building at southwest corner of site

Location: Gary Development Landfill, Gary, Indiana

Date/Time Taken: 09/05/2012 at 10:28 AM



Photo 4 (100_0007): Abandoned tanker truck (view facing southeast)

Location: Gary Development Landfill, Gary, Indiana

Date/Time Taken: 09/05/2012 at 10:31 AM

Site: Gary Development Landfill – 459 N. Cline Avenue, Gary, Indiana

Description: Site Reconnaissance on September 5, 2012

Photographs taken by: U.S. Environmental Protection Agency



Photo 5 (100_0009): View of warbler bird perched near the Grand Calumet River

Location: Gary Development Landfill, Gary, Indiana

Date/Time Taken: 09/05/2012 at 10:39 AM



Photo 6 (100_0013): Probable Point of Entry (PPE) of landfill discharge to the wetland (view facing northwest)

Location: Gary Development Landfill, Gary, Indiana

Date/Time Taken: 09/05/2012 at 10:44 AM

Site: Gary Development Landfill – 459 N. Cline Avenue, Gary, Indiana

Description: Site Reconnaissance on September 5, 2012

Photographs taken by: U.S. Environmental Protection Agency



Photo 7 (100_0011): Probable Point of Entry (PPE) and water collection pond (view facing northwest)

Location: Gary Development Landfill, Gary, Indiana

Date/Time Taken: 09/05/2012 at 10:41 AM



Photo 8 (100_0014): View of man-made path along the southern edge of the site (view facing east)

Location: Gary Development Landfill, Gary, Indiana

Date/Time Taken: 09/05/2012 at 10:50 AM

Site: Gary Development Landfill – 459 N. Cline Avenue, Gary, Indiana

Description: Site Reconnaissance on September 5, 2012

Photographs taken by: U.S. Environmental Protection Agency



Photo 9 (100_0016): View of wetland area along the Grand Calumet River from the southeast corner of the site (view facing west)

Location: Gary Development Landfill, Gary, Indiana

Date/Time Taken: 09/05/2012 at 11:01 AM



Photo 10 (100_0017): Wetland area along the southeastern edge of the site (view facing west)

Location: Gary Development Landfill, Gary, Indiana

Date/Time Taken: 09/05/2012 at 11:03 AM

Site: Gary Development Landfill – 459 N. Cline Avenue, Gary, Indiana

Description: Site Reconnaissance on September 5, 2012

Photographs taken by: U.S. Environmental Protection Agency



Photo 11 (100_0018): A beaver-chewed tree next to the lagoon in the northwest portion of the site

Location: Gary Development Landfill, Gary, Indiana

Date/Time Taken: 09/05/2012 at 11:22 AM



Photo 12 (100_0021): View of the northern lagoon and submerged equipment (view facing south)

Location: Gary Development Landfill, Gary, Indiana

Date/Time Taken: 09/05/2012 at 11:23 AM

Site: Gary Development Landfill – 459 N. Cline Avenue, Gary, Indiana

Description: Site Reconnaissance on September 5, 2012

Photographs taken by: U.S. Environmental Protection Agency



Photo 13 (100_0024): View along the northern lagoon and Vulcan Materials Company (view facing west-southwest)

Location: Gary Development Landfill, Gary, Indiana

Date/Time Taken: 09/05/2012 at 11:25 AM



Photo 14 (100_0026): Non-hazardous waste drums on Vulcan's property near entrance to the site (view facing northeast)

Location: Gary Development Landfill, Gary, Indiana

Date/Time Taken: 09/05/2012 at 11:46 AM















